

Best of Show Coach Works
A Division of B. O. S. Company LLC

1011 Rancheros Drive

San Marcos CA 92069

Phone: (760) 480-0227 • Fax: (760) 480-0277

FINAL VEHICLE DELIVERY RELEASE

Upon the date that Tommy Lau, owner of a 1967 Chevrolet Camaro, VIN# 124377L114151, License# TOMSKIT & incoming mileage of 6822 takes possession of above vehicle from Best of Show Coach Works LLC acknowledges the completion of Hagerty Insurance claim # CE013649 (including owner requested changes to claim related operations) and owner requested customer pay repair operations (color change, additional repairs & added parts) to his satisfaction. This document releases Best of Show Coach Works LLC from further liability for mechanical operations that may be related to the Hagerty insurance claim & further states that any insurance related mechanical issues and negotiations will be processed by Mr. Lau & his appointed mechanic directly to Hagerty Insurance. Best of Show Coach Works LLC is not responsible for any further mechanical operations related to the installation or performance of the owner directed engine and additional performance parts exchange.

Mr. Lau has been refunded by Best of Show Coach Works LLC money for operations & parts that were not completed or replaced that were billed to and paid for by Hagerty Insurance on the original estimate & the supplemental billings by mutual agreement

Signed: Tommy Lau

Print name Tommy Lau

Signature *Tommy Lau*

Date 12-1-08

Signed: Richard Kvamme managing member of Best of Show Coach Works LLC

Print name Richard Kvamme managing member of Best of Show Coach Works LLC

Signature *Richard Kvamme*

Date 12-1-08